



# **Paslode**<sup>®</sup> *Impulse*<sup>®</sup>

**PPN50Xi**







= 13000 max



ON



OFF







		
	15 min.	2 500 max.
	60 min.	10 000 max.
	90 min.	13 000 max.





25%	50%	75%	100%
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>





0 → 300	<input type="checkbox"/>
	<input type="checkbox"/>
	<input type="checkbox"/>
	<input type="checkbox"/>
	<input checked="" type="checkbox"/>






-15°C	1 000 /hour
≤ T ≤	
+49°C	3 300 /day





















**RESET**



Resting position / Ruheposition / Position de repos / Ruststand / Posición de descanso / Posizione di riposo / Posição de descanso / Pozycja spoczynku / Klidová poloha / Nyugalmi állapot / Положение в нерабочем состоянии / Θέση αδράνειας / Hvilestilling / Viloläge / Hvileposisjon / Lepoasento / Položaj mirovanja / Pokojová poloha / Položaj mirovanja / وضع الشكون / Ramybės padėtis / Ooteasend / Miera stāvoklis / Hvíldarstaða





# Notes





ON



OFF






### PPN50Xi

Ø = 4 mm

L = 35 - 40 - 50 mm

Hardened Ring Nails



Route de Lyon F-26500 Bourg-lès-Valence

019691-1

03/2020